



Test Report

No. NGBEC1100467901

Date: 07 Jul 2011

Page 1 of 7

CIXI KAIFENG ELECTRONIC CO.,LTD

NO.118 DEVELOPMENT ROAD, XIAOLIN ROAD, XIAOLIN TOWN, CIXI, ZHEJIANG, CHINA

The following sample(s) was/were submitted and identified on behalf of the clients as : KF2EDG

SGS Job No. : NP11-000550 - NB

Sample May Cover : KF300,KF300R,KF305,KF306V,KF306R,KF705,KF705A,KF330,KF301,KF301R,
KF302,KF360,KF332,KF332N,KF350V,KF396V,KF350R,KF396R,KF125V,KF12
6V,KF126R,KF166,KF167V,KF167R,KF168,KF169,KF170V,KF170R,
KF102,KF103, KF104, KF120, KF124, KF127, KF128V,KF128R,KF128G,
KF128DG,KF129V,KF129R,KF635,KF950,KF950A,KF135,KF136,KF137,KF2ED
G,KF2EDGV,KF2EDGR,KF2EDGCV,KF2EDGCR,KF2EDGKA,KF2EDGLC,KF2
22,KF222V,KF22R,KF223,KF223V,KF223R,HT396,HT396V,HT396R,HT508,HT
508V,HT508R,KF141,KF142,KF124B,KF188,KF250,KF246,KF1026,KF8H(WP),
KF10H(WP),KF12H(WP),KF14H(WP),KF20H,KF100,KF186,KF25,KF30,KF35,K
F45,KF55,KF65,HB635,HB762,HB825,HB850,HB950,KF11,KF69,KF89,804,804
W,KF14,KF1001,KF1002,KF1003,KF7620,KF8500,KF1000,KF10000,KF1027,K
F1004,KF1005,KF1013,KF1014,KF1015,KF1016,KF1017,KF1043,
KF1045,KF1048,KF1020,KF1019,KF1060,KF1021,KF1071,KF1023,KF1024,KF
1009,KF1022,KF1086,KF1089,KF1093,KF1094,KF1011,KF006,KF1007,KF1010
,KF1098,KFD01,KFD02,KFD03,KFD04,KFD05,KFD06,116,KFXY130A/H/T/V/R,
KFXY130B/H/T/V/R,KFXY132/H/T/V/R,KFXY133/H/T/V/R,
KFXY134/H/T/V/R,KFXY135/H/T/V/R,KFXY136/H/T/V/R,KFXY137/H/T/V/R,5121
,5224,5521,5621,5388,5227,53A88,5224,616

Date of Sample Received : 24 Jun 2011

Testing Period : 24 Jun 2011 - 07 Jul 2011

Test Requested : Selected test(s) as requested by client.

Test Method : Please refer to next page(s).

Test Results : Please refer to next page(s).

Conclusion : Based on the performed tests on submitted samples, the results comply with the
RoHS Directive 2002/95/EC and its subsequent amendments.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/terms_and_conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To ensure the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com

SGS-CTI Standards Technical Services Co., Ltd.
Ningbo Branch

1-2/F West No. 4 Building, Lingyun Industry Park, No.1177 Lingyun Road, Ningbo National Hi-Tech Zone, Ningbo, China 315040 t E&E (86-574) 89070224 f E&E (86-574)87782095 www.cn.sgs.com
中国·宁波·国家高新区凌云路1177号凌云产业园4号楼西1-2,5层 邮编: 315040 HL: (86-574) 89070209 HL: (86-574)87768122 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)



Test Report

No. NGBEC1100467901

Date: 07 Jul 2011

Page 2 of 7

Signed for and on behalf of
SGS-CSTC Ltd.

LiuXiaoRong, Sharon
Approved Signatory

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/terms_and_conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: For the authenticity of testing inspection report & certificate, please contact us at telephone: (86-755)83071443 or email: CN.Doccheck@sgs.com

SGS-CS Standards Technical Service Co., Ltd.
Ningbo Branch Testing Center / Calibration Laboratory

1-2/5F West No. 4 Building, Lingyun Industry Park, No.1177 Lingyun Road, Ningbo National Hi-Tech Zone, Ningbo, China 315040 t E&E (86-574) 89070224 f E&E (86-574)87782095 www.cn.sgs.com
中国·宁波·国家高新区凌云路1177号凌云产业园4号楼西1-2,5层 邮编: 315040 HL: (86-574) 89070209 HL: (86-574)87768122 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)